

Download Bmw Manual Gearbox Shift Pin Repair

Transmission hard to shift E36/7, E38, E39, E46 E53 with S5D 260Z/280Z/310Z/320Z (C-
transmission)MANUAL GEARBOX Repair procedures that differ are identified as follows: PGI' - gearboxes
up to No. 7999999 ... 89. Shift shaft 90. Roll pin - Sth/reverse selector 91. Gear selector - Sth/reverse gears ...
Two types of manual gearbox are fitted to the Rover 800 range, type PGI which is fitted to 2.0 engine models ...
SSP308 Direct Shift ...How to: Service your transmission shift pins. Revision 1.0 Feb. 15, 2010 ... Step 5:
Remove reverse and 5th gear shift pin bushings. ... Orient the ramp on the 5th gear pin towards the top of the
transmission and insert the pin (BMW 23317502165) into the lower pin bushing (fig. 07-01). ...Shift Pin
Bushing Kit: <http://amzn.to/2vTwf9F> Shift Pin Service Tool: <http://amzn.to/2wdAKhQ> Bearing Puller Slide
Hammer Kit: <http://amzn.to/2vTchfb> Harbor Freight ...